



Das Auto.

Technical Bulletin

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Touareg	2011-2013	All	All	All	All

Condition

91 13 22 September 25, 2013 **2031434** Supersedes TB V911301 dated January 8, 2013 to update software level.

RNS 850 Radio Software Update

Customer may report one of the following concerns:

- HD Radio does not play back in stereo (plays in mono)
- Intermittent erratic display problems
- Displayed radio station does not match the station being played

Technical Background

Continual improvements to RNS 850 software provides solutions to issues experienced in the field.

Production Solution

Improved software.



Das Auto.

Technical Bulletin

Service

Software update procedure

- Connect Midtronics InCharge 940 (INC 940) Tester/Charger to vehicle's battery if not done so already.
- Install the update DVD with the markings facing upwards into the internal drive of the J974 located in the passenger glove compartment, then wait a minimum of 2 minutes to allow the system to completely start up and the update menu becomes available.
- Push and hold the **SETUP** and **PHONE** buttons simultaneously for 5 seconds (See Figure 1).




Figure 1



Tip: Push the “SETUP” button moments before the “PHONE” button if unit will not enter “Engineering” mode.

- After 5 seconds, the Engineering Menu display should be visible (See figure 2). Select “Update”.




Das Auto.

Technical Bulletin



- After ~5 seconds the Engineering menu will be displayed.
- Confirm software level is below "0711".
- Press the "Update" button.



- Press "CD/DVD".




Das Auto.

Technical Bulletin



- This screen will appear momentarily.




- Press "HN+_US_VW_P0711."




Das Auto.

Technical Bulletin



- Press "Standard".



- Press "Start download".



Das Auto.

Technical Bulletin



- Press "Start".



- This screen will appear and the system will shut down.




- Radio will turn itself back on. No user input is required.




Das Auto.

Technical Bulletin




- As update progresses several screens like this will appear.
- Each will update to 100% then continue to next.



After individual updates are downloaded the unit will re-boot 4 times.


**Note: No user input is required.
DO NOT press the return button.
Allow unit to proceed uninterrupted**

Technical Bulletin



After downloads are complete this screen will appear. No user input is required.

Note: DO NOT press the return button or Cancel. Allow unit to proceed uninterrupted




- Once the software update has completed press "Continue".



Das Auto.

Technical Bulletin



- Once screen appears the update is complete.
- Press "Cancel documentation".
- Remove DVD.

It is possible that one or more DTCs may now be present in the 5F – Information Electronics Module. These DTCs must be cleared using the following procedure.

Erasing DTCs:



Tip:

VAS Tester must have an internet connection to complete the procedure.



Note:

Prior to launching VAS-PC application and starting this procedure, confirm tester screen saver and power settings in accordance with Special Tools and Equipment - Service Information Circular # VSE-08-18. Failure to do so may result in the tester entering power save mode during data transfer, and subsequent control module failure.


When using a VAS 6150, 5051B or 5052A tester in conjunction with a VAS 5054A wireless transmitter head for a flash procedure, please connect a USB cable between the transmitter head and the tester. Failure to do so may lead to errors during the flash procedure.

- Access Test Plan 5F – Installation status test/reset DTC memory will be shown:



Das Auto.

Technical Bulletin



- Follow the test plan. When instructed, enter in Unit Code **3380**.



Tip:

Erroneous DTCs will be cleared in the system upon completion of the test plan.

During update any paired Bluetooth devices may be deleted. It may be necessary to re-pair device(s) after update is complete.