

Technical Bulletin



Condition

**REQUIRED VEHICLE UPDATE TECHNICAL BULLETIN (RVUTB)
PERFORM ON ALL APPLICABLE VEHICLES WITHIN THE LIMITED NEW VEHICLE WARRANTY**

94 07 04 Sept. 10, 2007 2015991

RVU- Headlights Remain On in Full Sunlight (OK)



Tip:

Technical Bulletin Expiration Date: September 10, 2008

Headlights may remain on in full sunlight when the headlight switch is in the “auto on” mode.

Technical Background

The **Central Electrics Module** is found to be incorrectly coded. This causes headlights to remain on when in full sunlight

Production Solution

Production corrected as of VIN: **8W069031**.

Service

Requirements:

Vehicle must meet **ALL** of the following criteria:

VIN must show **(OK)** code open in ElsaWeb **on the day of repair.**

Vehicle must be within the Limited New Vehicle Warranty.

Repair must be performed prior to the expiration date listed in this technical bulletin.



Tip:

Procedure must also be performed on applicable vehicles in dealer inventory.

PROCEDURE:

Use the following procedure to check and / or change Central Electrics Control Module coding.

Technical Bulletin



Tip:

To check functionality the vehicle must be in natural sunlight. Flashlights, fluorescent shop lights etc. will not activate the feature.

Enter Vehicle Self Diagnosis using VAS 5051A/B or VAS 5052.

Highlight “On Board Diagnostics (OBD)” and select forward arrow.

Highlight “09 – Electronic Central Electrics” and select forward arrow.

Highlight “007 Coding (Service 1A)” and select forward arrow.

Highlight “Central Electrics Part Number” and select forward arrow.

Highlight Byte 0.

If Byte 0 is “F6” then **DO NOT** change any values and exit this procedure.

If Byte 0 is not “F6” then type in “F6” and click on “Q”.

Confirm coding and exit.

Technical Bulletin



Warranty

Claim Entry Procedure

Immediately upon completion of the repair work, enter the correct code listed below. Claims will only be paid for vehicles that show this RVU open in ElsaWeb on the day of repair. To help ensure prompt and proper payment, attach the screen print to the repair order.

Additional Actions

Some of the affected vehicles may be involved in additional actions, recalls or service campaigns. Please check ElsaWeb so that any additional required work can be done simultaneously.

Claim Help

Contact the Warranty Helpline toll-free at 1-866-306-8447 for help with claim entry.

Required Customer Notification

Inform your customer in writing by recording on the Repair Order any and all work that was conducted on the vehicle, including any and all updates completed under this RVU.

WIN System Claim Entry Procedure	Use Claim Type RC		
	Damage Code	Time Units	Work Scope
	OK 11	20 T.U.	Check coding; no update required.
	OK 12	20 T.U.	Check coding; update coding
	OK 20	0 T.U.	Customer refused repairs
	There is no reimbursement for vehicle wash or loaner vehicle. The system will enter labor & parts applicable to the codes above.		

Technical Bulletin



OK SAGA Claim Entry Procedure

Check in the system Service-Online, FISH (VSI), to determine whether this RVU is open.

Service No.: 97M4

Damage Code: 0066

Parts Manufacturer – Removed part:

Please use the vendor code from the removed part. If no vendor code is available, then use K21.

Claim Type

Sold vehicle = 7 10

Unsold vehicle = 7 90

Accounting Instructions

Criteria I.D. 01 Check coding; no update required

Repair operation: 0183 00 99 20 TU

OR

Criteria I.D. 01 Check coding; update coding

Repair operation: 9794 25 99 20 TU

There is NO reimbursement for Wash or Loaner Vehicle!

If Customer refused repairs

Fax the Repair Order to VWoA at (248) 754-5093 and provide VIN, applicable Service Number, Customer Information, Dealer Number and Date

Technical Bulletin



Required Parts and Tools

No Special Parts required.

No Special Tools required.